

Verification

Software status should be follow looking at this 4 non regression tests:

	Python	c++
fifo (up-down links links)	BT didn't works	using FC instead of BT
rng (speed download link)	register order change	didn't works after a soft reset
config (configure)	do not use headers	sometime loose the last word
driver (read-out)	ok	ok

note: fifo and rng tests only access the DIF, where config and driver tests go up to the ASICS.